



From left:

5 x 20 mm glass fuse

Wickman

Mini fuse 7 x 2 mm

SMD mini fuse (only to be soldered).

IMPORTANT!

When you set out to change a fuse remember the risks associated with electricity and take all necessary precautions. Always turn the main power switch off before beginning work, and if in doubt about anything stop and contact a licensed technician.